

Part Number: 2042200-103

Replaces Bell P/N 204-011-702-15

Fleet Adoption: FAA STC/PMA. Flying in Australia, Canada, Chile, Mexico,

New Zealand, Philippines, South Africa, and U.S.

Service Life: 2,400 hours

1,200 hours for Bell P/N 204-011-702-15

**Construction:** Corrosion-resistant **carbon fiber** spar and skin construction,

closed cell structural foam interior, fiberglass root fitting

Leading Edge Protection: Stainless steel abrasion strip along entire length of leading edge

for leading edge fidelity and erosion protection

Airfoil Design: Boeing VR-7 laminar flow airfoil for improved efficiency

Paint: Nano hybrid polyurethane (NHP) topcoat for increased

durability, flexibility, and corrosion resistance

Performance: Increased tail rotor authority

**Installation:** Direct replacement without hub modification



1.530.365.1278

pablo@helicopterbladerepair.com 19797 Riverside Ave • Anderson, CA 96007 USA