

Part Number: 20635000-501

Replaces Bell P/N 206-010-200-133, -137, -139, -145, -149, -151

Certification: FAA STC/PMA SR02732LA Issued August 2020

Service Life: 10.000 hours

5,000 hours for Bell P/N 206-010-200-133, -137, -139, -145, -149, -151

Construction: Corrosion-resistant **carbon fiber** spar and skin construction,

closed cell structural foam interior, titanium attachment plates

Leading Edge Protection: Stainless steel/nickel abrasion strips along entire length of

leading edge for leading edge fidelity and erosion protection

Airfoil Design: NASA RC(4)-10 laminar flow airfoil for improved efficiency

Paint: Nano hybrid polyurethane (NHP) topcoat for increased

durability, flexibility, and corrosion resistance

Performance: 3-5 kt increase in speed

Installation: Direct replacement without hub modification



1.530.365.1278

pablo@helicopterbladerepair.com 19797 Riverside Ave • Anderson, CA 96007 USA